



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 04/15/2015

Reviewed 

Mine Name: Leamington Cement Plant	Permit Number: M/023/0004	Mine Status: Active
Operator Name: Ash Grove Cement	Inspection Date: 04/07/2015	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 10:35 - 11:00 pm	Bond Amount: \$6,857,000
Attendee(s): Josh Nelson, Gordon Jarrett	Weather: mild and sunny	Bond Escalation: 07/22/2017
Inspection Purpose: Routine inspection		Prior Inspection: 06/05/2014

Conclusions and Recommendations

The permit is in good standing. The Permittee does not anticipate any new permitting actions at this site in the near future. The Division should continue to monitor the site annually

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds Permit fees and bonds are current. NOI is in good standing, no new permitting actions are proposed.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) There are no underground openings (except for blast holes) on site. The highwalls are part of the active mine operations.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control The site has ditches that convey runoff. The ditches were in working order and there was no sign of erosion problems.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) The roads are in good shape. The Permittee uses water to control dust	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation There were no reclamation activities on site. Because of the nature of mining no reclamation is feasible at the present time or in the near future.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/M0230004-Leamington/Inspections/Inspect0407AA.pdf



Mine looking south. Notice the highwalls on the left.



Mine looking south. Notice the road going up the mountain in the center of the photo. The Operator plans on doing more work on top the mountain later in the year.



Close up of the highwalls



Looking south, notice the haul roads and the large trucks that are used.



Material is pushed off the slope and then loaded onto trucks



Truck and loader on site.



Northern quarry



Notice the drill rig used for blasting in the center of the photo.